U.S. Department of Transportation

United States Coast Guard

LOCAL NOTICE TO MARINERS

JUNE WEEKLY SUPPLEMENT

NOTICE NUMBER 24-97

June 10, 1997

Issued by: Commander, Seventh Coast Guard District (oan)

Brickell Plaza, Federal Building

909 S.E. 1st Avenue, Miami, Florida 33131-3050

Telephone (305) 536-5621 (Office hours 7:30 a.m. - 4:00 p.m., M-F)

BROADCAST NOTICE TO MARINERS

Navigation information having been of immediate concern to the Mariner, and promulgated by the following broadcasts, has been incorporated in this notice when still effective:

- CCGD7 (D7) BNM 591-97 TO 617-97
- GROUP CHARLESTON (CHA) BNM 296-97 TO 318-97
- GROUP MAYPORT (MAY) BNM 342-97 TO 367-97
- GROUP MIAMI (MIA) BNM 291-97 TO 303-97
- GROUP KEY WEST (KEY) BNM 071-97 TO 081-97
- GROUP ST. PETERSBURG (STP) BNM 370-97 TO 377-97
- SAN JUAN (SJ) BNM 222-97 TO 234-97

NOTES: (1) Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution.

(2) A dark vertical line in the left margin indicates new information.

(3) The Local Notice to Mariners consists of a Monthly Edition and Weekly Supplementals. The Monthly Edition should be maintained as a reference. Recurring information is published only once a month.

REFERENCES: Light List, Vol. III, Atlantic and Gulf Coasts, 1996 Edition (COMDTPUB P16502.3).

U.S. Coast Pilot 4, Atlantic Coast: Cape Henry to Key West (31st Edition).

U.S. Coast Pilot 5, Atlantic Coast: Gulf of Mexico, Puerto Rico, and Virgin Islands (26 th Edition).

* * * * * * * * *

REPORT DISCREPANCIES IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

* * * * * * * * *

I. SPECIAL NOTICE

LORAN-C OPERATIONS, LORAN STATION SENECA STATUS

The Coast Guard proposes to authorize Loran Station Seneca (Rate 9960-M/8970-X) off-air time from 1400Z to 1600Z on July 15, 1997. The alternate time will be from 1400Z to 1600Z on July 17, 1997. Objections will be considered until 1600Z, July 08, 1997. Users shall address inquiries to the Northeast Coordinator of Chain Operations at (607) 869-1334. Current Loran-C status is available 24 hours-a-day through an electronic bulletin board system (BBS) at (703) 313-5910, baud rate 300 to 28,800. The communication parameters are eight bit word, one stop bit, no parity. Internet Address: HTTP://WW.NAVCEN.USCG.MIL, FPT://FTP.NAVCEN.USCG.MIL.

EXCERPT FROM FEDERAL REGISTER ARTICLE -

Security Zone' Coast Waters Adjacent to South Florida

The following information is an excerpt of Federal Register, Vol. 62, No. 93, Wednesday, May 14, 1997, Pages 26390 - 26392.

Agency: Coast Guard, DOT. Action: Temporary Final Rule.

SUMMARY: Pursuant to Presidential Proclamation No. 6867, declaring a national emergency, the Coast Guard, after consultation with the Department of justice, is establishing a revised security Zone, restricting the operation of certain vessels within the internal waters and territorial seas of the United States, adjacent to or within the coastal waters around southern Florida. The Coast Guard Captain of the Port (COTP) may exercise complete control over all vessel operations and movements within the security zone. Non-public vessels of less than 50 meters (165 feet) in length, may not get underway in or depart the security zone with the intent to enter Cuban territorial waters, absent express authorization from the COTP. These vessel control measures are necessary to provide for the safety of United States citizens and residents and to prevent threatened disturbance of the international relations of the United States.

EXCERPT FROM FEDERAL REGISTER ARTICLE - Security Zone' Coast Waters Adjacent to South Florida (Cont.)

DATES: This rule is effective from May 7, 1997, and will terminate when the National Emergency as declared by the President in Presidential Proclamation No. 6867 terminates. The Coast Guard will publish a separate document in the FEDERAL REGISTER announcing termination of the rule.

ADDRESSES: Permission of the COTP to depart the security zone with the intent of entering Cuban territorial waters may be obtained from the following U.S. Coast Guard units: Marine Safety Office Miami, 51 S.W. First Avenue, Miami, FL 33130, ph.(305) 536-5693; Marine Safety Office Tampa, 155 Columbia Drive, Tampa, FL 33603, ph.(813)228-2195; Station Miami Beach, 100 MacArthur Causeway, Miami Beach, FL 33139, ph.(305) 535-4368; Station Fort Lauderdale, 7000 N Ocean Dr., FL 33004, ph.(305)927-1611; Station Marathon, 1800 Overseas Highway, Marathon, FL 33050, ph.(305) 743-1945; Station Islamorada, PO Box 547, 183 Palermo Dr, Islamorada, FL 33036, ph. (305)292-8862; Station Key West, Key West, FL 33040, ph.(305) 292-8862; Station Fort Myers Beach, 719 San Carlos Drive, Fort Myers Beach, FL 33931, ph.(813) 463-5754. Additional locations may be established.

FOR FURTHER INFORMATION CONTACT: Chief, Marine Safety Division, Seventh Coast Guard District, 909 SE First Avenue, Brickell Plaza Federal Building, Miami, FL 33131, Phone (305)536-5651.

SAFE BOATING AND SEAMANSHIP COURSES

HOST DATES TIME LOCATION

U.S. Coast Guard Auxiliary Staring Jun 17, 1997 7:15 p.m. - 9:15 p.m. Piper

Community School

Flotilla 38 (Boating Skills & Seamanship) (Tuesdays and Thursdays) 8000 NW 44 St.

Dag Harms (954) 327-9199 (10 lessons) Sunrise, FL

Courses are free; however, there is a small fee for text, workbooks, etc.

II. NEW DISCREPANCIES-DISCREPANCIES CORRECTED

The following is a partial list of aids that were not watching as advertised in the Light List as of 1:00 a.m. on the date of this Notice and a list of aids previously reported discrepant that have been corrected since the last Local Notice to Mariners. Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution. For a complete list of discrepancies and for descriptions of abbreviations see Monthly Local Notice to Mariners 22-97.

FEDERAL AID DISCREPANCIES:

LLNR	AID NAME	DISCREPANCY	/	CHARTBNM	LNM				
00615 00775 01305 01745	Miami LWB M Sand Key LT Murrells Inl DE Bulls Bay LB 2	3N 9	BUOYS LT EXT TRUB MISSIN	Γ	11441 11534	080-97 303-97		24/97 24/97	24/97 24/97
02215	Town Cr Ch L		OFF S				294-97		24/97 24/97
03265	N Edisto Riv E		LT IMC		11522	N/A		24/97	
03420	Egg Bank DBI		DBN D			11517			24/97
04980	Wassaw Snd I		MISSIN	NG MISSING		11509	N/A	NI/A	24/97
04985 24/97	Wassaw Snd I	LD 0		MISSING			11509	IN/A	
06290		Rng E Rear LT		LT DIM		11503	367-97	-MAY	24/97
06460	St Johns Riv E			LT EXT		11490	357-97		24/97
06465 24/97	St Johns Riv E	Ent LB 4		OFF STA			11490	358-97	-MAY
07230	Forrester Pt L	T 41	LT EX	Г	11492	338-97	-MAY	24/97	
07285	Rice Cr Ent Cl			LT EXT			337-97	-MAY	24/97
08550	St Augustine I		DBN D	EST		11485	365-97	-MAY	24/97
09210	St Lucie Inl DE	BN 17	TRUB		11472	301-97	-MIA	24/97	
09420	Miami LWB M		BUOYS			11468	303-97		24/97
09745 24/97	Miami Riv Ch	DBN 3		DBN DMGD			11468	N/A	
30550	Little Riv-Winy	ah Bav LT W		DBN DEST			11532	318-97	-CHA
24/97	,	,							
31445	White Pt LT 1	10	TRLB		11522	315-97	-CHA	24/97	
33225	Doboy Is DBN		DBN D				355-97		24/97
34090		Rng E Rear LT	TOUR	LT DIM	4.4.400	11503	367-97		24/97
34910	Pablo Cr DBN		TRUB		11489		NALA	24/97	
45930	Woods Pt DBN	N 3	TRUB		114/2	291-97	-IVIIA	24/97	

FEDERAL DISCREPANCIES CORRECTED:

LLNR	AID NAME	STATUS	CHART	BNM	LNM					
00745 04060 05130 06220 23/97	Occahaw Snd	Obst B 3	WATCI	HING F	TON ST	LY	11512			12/97 24/97 24/97 -MAY
06495 24/97	Mayport Basir	n RRL		WATO	CHING P	ROPERL	Υ.	11488	344-97	-MAY
06560 07020 09275 09440 24/97	Mayport Cut F Ortega Riv LT Lake Worth Ir Miami Main C	⁻ 1 nl LT 9	RELIGI WATCI RELIGI	HING F HTED	PROPER	LY	292-97	361-97 -MIA	24/97 -MAY 24/97 298-97	24/97 -MIA
20025 23/97	Pt Manatee C	h LB 6		WATO	CHING P	ROPERL	Υ.	11414	352-97	-STP
20095 23/97	Tampa Bay C	ut C Ch LB 5C		WATO	CHING P	ROPERL	Υ.	11414	370-97	-STP
20675 28003 28450 LLNR	Alafia Riv DBI Radas Roose Bahia de Talla AID NAME	N 11 velt Passage LB : aboa LB 4 STATUS	3	RESE		D FATION FATION	25663			23/97 24/97 02/97
28515 23/97	Bahia de Gua	yanilla LB 1		WATO	CHING P	ROPERL	Υ.	25681	214-97	-GSE
28745 30610 10/97		ona E Shl LB 6 yah Bay LT 100			— —	ROPERL	25671 .Y	N/A 11532	N/A	24/97
31810 32115 32145 32605 23/97	Brickyard Cr F Skull Cr DBN Skull Cr DBN Skidaway Riv	4 9A	REBUI	LT/RE(LT/RE(PROPER COVERE COVERE JILT/REC	D	11516 11516	300-97- 247-97- 197-97- 11512	-CHA	24/97 21/97 19/97 -CHA
34165 23/97	Cumberland S	Snd Lower Rng C	RFL	WATO	CHING P	ROPERL	Υ.	11503	342-97	-MAY
34365 35475 24/97	Fernandina B San Sebastia	ch LT 1 n Riv DBN 9				ROPERL	11503 .Y		-MAY 359-97	
35680 36305 37010	Matanzas Riv Halifax Riv Lt New Smyrna	23	RELIG	HTED	OHTED CHING P	11485 ROPERL			24/97 356-97	24/97 -MAY
24/97 40695	Indian Riv S S	Sec LT 182		RELIC	SHTED		11472	295-97	-MIA	24/97

PRIVATE AID DISCREPANCIES:

LLNR AID NAME DISCREPANCY CHARTBNM LNM

None.

PRIVATE DISCREPANCIES CORRECTED:

LLNR	AID NAME	STATUS	CHART	BNM	LNM					
23905	*Aripeka DBN		WATC			RLY				20/97
24065 21/97	*Cutter Rock (Obstr LT		WATO	CHING F	PROPER	LY	11409	317-97	-STP
24165	*Hernando Bc	h Ch DBN 17		WATO	CHING F	ROPER	LY	11409	N/A	
20/97	*Hernando Bc	h Ch DDN 22		\\/ \ T(ROPER	V	11409	NI/A	
24230 20/97	Hemanuo BC	II CII DBN 32		WAI	JUING E	KOPEK	∟ ĭ	11409	IN/A	
24375	*Hernando Bc	h Ch DBN 70		WATO	CHING F	PROPER	LY	11409	N/A	
20/97	*D (Ob	NDN 454		\A/A T /		NDODED		44400	400.07	OTD
24645 12/97	*Bayport Ch D	JBN 15A		WAIC	HING F	PROPER	LY	11409	180-97	-SIP
24795	*Chassahowitz	zka App LT CW		WATO	CHING F	ROPER	LY	11409	0709-9	6-STP
36/96										
25695 50/96	*Florida Powe	r Corporation Ch	LT 41	WATO	CHING F	PROPER	LY	11408	?	
26875	*Salt Creek DI	BN 17	WATC	HING F	PROPER	RI Y	11408	?		35/94
48503		ht Club Ch DBN				ROPER		11428	N/A	00,0.
06/97										
48503	*Caloosa Yach	ht Club Ch DBN	2	WATO	CHING F	PROPER	LY	11428	247-97	-STP
16/97	*Colone Van	at Club Ch DDN	2	\A/A T /			V	44400	247.07	CTD
48503 16/97	Caloosa Yaci	ht Club Ch DBN	3	WAI	JHING F	PROPER	L Y	11428	247-97	-511
50755 06/97	*Safety Hbr C	h DBN 11		WATO	CHING F	PROPER	LY	11426	N/A	

III. TEMPORARY CHANGES-AIDS ESTABLISHED:

LLNR	AID NAME	STATUS	CHART	ГВИМ	LNM				
Pa 31	Folly Riv B 9A	EST/SHI	11522	286-07	′-CH4	24-97			
	Folly Riv B 10A		_		_	24-97			
3140	Folly Riv B 11	RELOC/SHL	11522	288-97	-CHA	24-97			
Pg 31	Folly Riv B 12	EST/SHL	11522	289-97	-CHA	24-97			
Pg 31	Folly Riv B 14A	A EST/SHL	11522	290-97	'-CHA	24-97			
19335	Longboat Pass	DBN 3 DISCO	N/Dredg	jing	11425	354-97	-STP	24-97	
36750	Ponce de Leon	Cut DBN 2	TRUB/I	RELOC	/SHL	11485	343-97	7-MAY	24-97

TEMPORARY AIDS CORRECTED:

LLNR AID NAME STATUS CHARTBNM LNM None.

IV. CHART CORRECTIONS

(Explanation of Format)

Corrective action, affecting charts, is contained in this section. Chart corrections are listed numerically by chart number, beginning with the lowest and progressing through all charts affected. The correction

listed pertains to that chart only. It is up to the mariner to decide which charts are to be corrected. The following example explains the individual elements of a typical correction.

	Chart number			Last Local Notes to Mariners		Reference			Current Notice
	1	I	I	l l	I	I	. to man		
1153/	26 th ad	1 12/1//0	1	Last LNM 41	/Q2	l N	IAD 83(CG7)	06/93	
							MD 03(CG1)	00/93	
(Temp)	Myrtle G	Grove So	ound to	Fear River to	Casino Cre	eek			
	Add	Boguse	Channe	el Light 1, Fl G	3 2.5s, 16 f	ft, 7M			32 ² 48'00"N
79 ² 15'0)0"W	_		_					
	:								
Cor act	rective ion		Object action	of corrective	Positio	n			

The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (M).

```
45<sup>th</sup> ed., 10/12/96 LAST LNM 21/97 NAD 83
                                                                                       24/97
       Gulf of Mexico
                                                                                       (CGD07)
        CHANGE
                       Cape Canaveral Lt to 24M in
        28227'37.3"N 080232'36.4"W
    (Previously Temp Changed 04/96)
   (CGD07)
        DELETE
                       NOAA Data LB "41006" from
       29218'07.0"N 077222'52.7"W
11009 34<sup>th</sup> ed., 01/23/93 LAST LNM 21/97 NAD 83
                                                                                       24/97
       Cape Hatteras to Straits of Florida
        (CGD07)
       CHANGE
                       Cape Canaveral Lt to 24M in
        28<sup>2</sup>27'37.3"N 080<sup>2</sup>32'36.4"W
   (Previously Temp Changed 04/96)
    (CGD07)
        DELETE
                       NOAA Data LB "41006" from
       29218'07.0"N 077222'52.7"W
11013 42<sup>nd</sup> ed., 07/13/96 LAST LNM 17/97 NAD 83
                                                                                       24/97
        Straits of Florida and Approaches
                                                                                               (NOS
SILVER SPRING)
                       light symbol and text: F 114M at
        DELETE
       22207'00.0"N 077239'00.0"W
11413 42<sup>nd</sup> ed., 09/21/96 LAST LNM 18/97 NAD 83
                                                                                       24/97
        Tampa Bay (Northern Part)
        (CGD07)
        RELOCATE
                       Alafia River Daybeacon "11" from
                (27251'8.603"N, 82224'32.672"W) to
                                                                                       27251'08.6"N
082224'32.5"W
11414 36<sup>th</sup> ed., 09/28/96 LAST LNM 23/97 NAD 83
                                                                                       24/97
       Tampa Bay (Southern Part)
```

Manatee River Daybeacon "10" from

(CGD07) RELOCATE

(27231'37.258"N, 82238'38.441"W) to 27231'37.1"N 082238'38.6"W Manatee River Daybeacon "16" from (27230'34.102"N, 82234'57.914"W) to 27230'34.0"N 082234'57.9"W 11425 31st ed., 10/05/96 LAST LNM 23/97 NAD 83 24/97 (TEMP) Charlotte Harbor to Tampa Bay (CGD07) DELETE Longboat Pass Daybeacon "3" from (For Dredging) (Side B) 27226'28.2"N 082241'41.9"W 11425 31st ed., 10/05/96 LAST LNM 23/97 NAD 83 24/97 Charlotte Harbor to Tampa Bay (CGD07) RELOCATE Siesta Key-Tampa Bay Daybeacon "50" from (27²28'48.129"N, 82²41'46.468"W) to (Side B) 27228'47.9"N 082241'46.7"W Manatee River Daybeacon "10" from (27231'37.258"N, 82238'38.441"W) to (Side B) 27231'37.1"N 082238'38.6"W Manatee River Daybeacon "16" from (27230'34.102"N, 82234'57.914"W) to (Side B) 27230'34.0"N 082234'57.9"W Siesta Key-Tampa Bay Lt "27" from (27²24'54.9"N, 82²38'53.0"W) to (Side B) 27224'55.4"N 082238'53.9"W 11426 33rd ed., 06/01/96 LAST LNM 17/97 NAD 83 24/97 Estero Bay to Lemon Bay (CGD07) **CHANGE** Safety Hbr Chan Lt "1" to Q G in (Priv maint) 26236'06.1"N 082212'50.1"W (CGD07) Spring Lake Waterway Jct Daybeacon "C" from (Priv maint) DELETE 26257'55.6"N 082207'02.8"W 11429 19th ed., 04/19/97 NEW EDITION 11BCO11429 NAD 83 24/97 (TEMP) Chatham River to Clam Pass (NOS SILVER SPRING) (New edition due to various general changes.) 1:80,000/Loran-C/\$14.00 Insets: EVERGLADES HARBOR 1:30,000 NAPLES BAY 1:30,000 (CGD07) 17/96 CHANGE Caxambas Bay Daybeacon "15" to - Buoy "15" and RELOCATE from 25254'20.3"N (25254'20.129"N, 81241'37.783"W) to 081241'37.8"W (CGD07) 33/96 Caxambas Bay Daybeacon "8" to - Buoy "8" in CHANGE 25254'06.2"N 081241'32.4"W (CGD07) 06/97

Gordon Pass Ch Temp Buoy "7" from RELOCATE (2625'34.4"N, 81248'00.3"W) to 26205'35.7"N 081247'54.3"W Gordon Pass Chan Temp Buoy "7A" from (2625'35.2"N, 81247'56.3"W) to 26205'35.4"N 081247'57.7"W 11429 19th ed., 04/19/97 NEW EDITION 11BCO11429 NAD 83 24/97 Chatham River to Clam Pass (NOS SILVER SPRING) 1:80,000/Loran-(New edition due to various general changes.) C/\$14.00 Insets: EVERGLADES HARBOR 1:30.000 NAPLES BAY 1:30,000 (CGD07) 19/97 Subm Wr (46 ft Trawler), clearance 5 ft in (PA) ADD 26205'23.0"N 081250'40.0"W 11460 34th ed., 11/02/96 LAST LNM 17/97 NAD 83 24/97 Cape Canaveral to Key West (CGD07) CHANGE Cape Canaveral Lt to 24M in 28227'37.3"N 080232'36.4"W (Previously Temp Changed 04/96) 11465 32nd ed., 04/05/97 NEW EDIITON 11XHA11465 NAD 83 24/97 Miami to Elliot Key (CGD07) (New edition due to various general changes.) 1:40,000/\$14.00 (CGD07) 19/97 Biscayne Chan Lt "1" from RELOCATE (2523841.282"N, 80282.072"W) to and REMOVE PA 25238'41.2"N 080208'02.4"W Biscayne Chan Lt "2" from (2523850.16"N, 80284.133"W) to and REMOVE PA 25238'49.6"N 080208'04.3"W Biscayne Chan Lt "3" from (252394.355"N, 802839.958"W) to and REMOVE PA 25239'03.9"N 080208'39.8"W Biscayne Chan Daybeacon "4" from 11465 RELOCATE (Cont.) (25239'7.118"N, 8028'37.108"W) to 25239'01.0"N 080208'35.9"W Biscayne Chan Lt "6" from (25239'13.874"N, 8028'58.831"W) to and **REMOVE PA** 25239'13.6"N 080208'58.7"W Biscayne Chan Daybeacon "7" from (25239'10.16"N, 8029'6.147"W) to 25²39'10.1"N 080²09'06.1"W Biscayne Chan Daybeacon "8" from

25239'12.9"N 080209'10.1"W

(25239'12.976"N, 8029'9.619"W) to

Biscayne Chan Daybeacon "10" from	
(25 ² 39'16.13"N, 80 ² 9'34.986"W) to	25 ² 39'16.0"N 080 ² 09'34.8"W
Biscayne Chan Daybeacon "12" from	
(25 ² 39'15.965"N, 80 ² 9'57.236"W) to	25²39'15.8"N 080²09'57.3"W
Biscayne Chan Daybeacon "14" from	
(25 ² 39'15.921"N, 80 ² 10'14.111"W) to	25 ² 39'15.7"N 080 ² 10'14.2"W
Biscayne Chan Lt "15" from	
(25 ² 39'7.029"N, 80 ² 10'27.808"W) to	25 ² 39'07.2"N 080 ² 10'28.1"W
Biscayne Chan Daybeacon "16" from	
(25 ² 39'15.427"N, 80 ² 10'29.227"W) to	25 ² 39'15.2"N 080 ² 10'29.3"W
Biscayne Chan Daybeacon "18" from	
(25 ² 39'14.806"N, 80 ² 10'49.726"W) to	25 ² 39'14.4"N 080 ² 10'49.8"W
Biscayne Chan Daybeacon "19" from	
(25 ² 39'17.847"N, 80 ² 11'5.404"W) to	25 ² 39'17.6"N 080 ² 11'05.7"W
Biscayne Chan Daybeacon "20" from	
(25 ² 39'23.74''N, 80 ² 11'6.88''W) to and	
REMOVE PA	25 ² 39'23.4"N 080 ² 11'07.0"W
Biscayne Chan Lt "21" from	
(25 ² 39'20.754"N, 80 ² 11'10.496"W) to	25 ² 39'20.3"N 080 ² 11'10.5"W
Soldier Key Daybeacon "2" from	
(25 ² 35'46.445"N, 80 ² 7'33.642"W) to	25 ² 35'46.6"N 080 ² 07'33.4"W
Fowey Rocks Daybeacon "3" from	
(25 ² 35'41.437"N, 80 ² 6'57.1"W) to	25²35'41.5"N
080 ² 06'57.0"W	00/07
(CGD07) RELOCATE Biscayne Chan Daybeacon "4"	23/97 from
(25 ² 39'.962"N, 80 ² 8'35.946"W) to 080 ² 08'36.7"W	25²39'06.6"N
Biscayne Bay Lt "59" from	
(25 ² 46'13.397"N, 80 ² 10'54.36"W) to	25 ² 46'13.1"N 080 ² 10'54.2"W
Biscayne Bay Daybeacon "61" from	
(25 ² 45'56.967"N, 80 ² 10'58.75"W) to	25 ² 45'55.3"N 080 ² 10'57.8"W
Biscayne Bay Lt "63" from	
(25 ² 45'41.528"N, 80 ² 11'3.602"W) to	25 ² 45'41.6"N 080 ² 11'03.5"W
Biscayne Bay Lt "64" from	
(25 ² 45'37.21"N, 80 ² 11'6.345"W) to	25 ² 45'37.1"N 080 ² 11'06.4"W
Biscayne Bay Daybeacon "65" from	
(25 ² 45'25.454"N, 80 ² 11'3.138"W) to	25 ² 45'25.0"N 080 ² 11'03.1"W
Biscayne Bay Lt "67" from	

(25 ² 45'8.955"N, 80 ² 11'2.401"W) to	25 ² 45'08.6"N 080 ² 11'02.4"W
Biscayne Bay Daybeacon "69" from	
(25 ² 44'32.119"N, 80 ² 11'.052"W) to and	
REMOVE PA	25 ² 44'31.3"N 080 ² 10'59.8"W
Biscayne Bay Lt "71" from	
(25 ² 44'13.274"N, 80 ² 11'.915"W) to	25 ² 44'13.0"N 080 ² 11'00.9"W
Biscayne Bay Lt "73" from	
(25 ² 42'34.52"N, 80 ² 10'58.463"W) to	25 ² 42'34.4"N 080 ² 10'58.5"W
Dinner Key Chan Daybeacon "6" from	
(25 ² 43'7.363"N, 80 ² 13'17.176"W) to	25 ² 43'08.3"N 080 ² 13'17.2"W
Key Biscayne Yacht Club Chan Lt "1" from	
(25 ² 41'59.142"N, 80 ² 10'46.25"W) to	25 ² 41'59.1"N 080 ² 10'46.4"W
Key Biscayne Yacht Club Chan Lt "3" from	
(25 ² 41'51.537"N, 80 ² 10'27.838"W) to	25 ² 41'51.3"N 080 ² 10'27.7"W
SW Shls Daybeacon from	
(25 ² 41'24.36"N, 80 ² 11'1.214"W) to	25 ² 41'24.1"N 080 ² 11'01.5"W
Biscayne Flats Daybeacon "1" from	
(25 ² 40'19.452"N, 80 ² 10'59.168"W) to	25 ² 40'22.0"N 080 ² 11'01.7"W
Biscayne Flats Daybeacon "3" from	
(25 ² 39'49.37"N, 80 ² 10'59.172"W) to	25 ² 39'49.7"N
080²11'01.2"W	
11467 33 rd ed., 12/14/96 LAST LNM 23/97 NAD 83 West Palm Beach to Miami (CGD07) RELOCATE Biscayne Chan Lt "6" from	24/97
(25 ² 39'13.874"N 080 ² 08'58.831"W) to (Side B)	
(Previously advertised incorrectly as LT "5"	
in LNM 19/97) 080 ² 08'58.7"W	25²39°13.6"N
11476 18 th ed., 01/07/95 LAST LNM 21/97 NAD 83 Cape Canaveral to Bethel Shoal (CGD07) CHANGE Cape Canaveral Lt to 24M in	24/97
28 ² 27'37.3"N 080 ² 32'36.4"W	
(Previously Temp Changed 04/96) 11477 5 th ed., 10/20/84 LAST LNM 21/97 NAD 27	24/97
Port Canaveral and Approaches	24/3/
(CGD07) CHANGE Cape Canaveral Lt to 24M in	
28 ² 27'37.3"N 080 ² 32'36.4"W	
(Previously Temp Changed 04/96)	
11480 33 rd ed., 04/06/96 LAST LNM 21/97 NAD 83	24/97

Charleston Light to Cape Canaveral (CGD07) **CHANGE** Cape Canaveral Lt to 24M in 28²27'37.3"N 080²32'36.4"W (Previously Temp Changed 04/96) 11481 2nd ed., 10/26/96 LAST LNM 21/97 WGS 84 24/97 Approaches to Port Canaveral (CGD07) CHANGE Cape Canaveral Lt to 24M in 28227'37.3"N 080232'36.4"W (Previously Temp Changed 04/96) 11484 19th ed., 03/05/94 LAST LNM 21/97 NAD 83 24/97 Ponce De Leon Inlet to Canaveral Harbor (CGD07) CHANGE Cape Canaveral Lt to 24M in 28227'37.3"N 080232'36.4"W (Previously Temp Changed 04/96) 11485 30th ed., 06/08/96 LAST LNM 20/97 NAD 83 24/97 (TEMP) Tolomato River to Palm Shores (CGD07) CHANGE Ponce de Leon Cut Daybeacon "2" to - Buoy "2" and RELOCATE from (29205'38.8"N 080256'57.6"W) to (Side A) 29205'38.8"N 080256'56.3"W 11485 30th ed., 06/08/96 LAST LNM 20/97 NAD 83 24/97 Tolomato River to Palm Shores (CGD07) Tolomato River Buov "58E" from RELOCATE (2925435.898"N, 8121748.943"W) to (Side A) 29254'36.2"N 081217'48.9"W 11506 37th ed., 05/04/96 LAST LNM 19/97 NAD 83 24/97 St. Simons - Brunswick Harbor and Turtle Bay (NOS SILVER SPRING) (CL-515/97) ADD Tabulations of Controlling Depths (See Enclosure Section) 11507 28th ed., 08/03/96 LAST LNM 23/97 NAD 83 24/97 SC - GA - Beaufort Riv - St. Simons Sound (CGD07) RELOCATE Vernon River Daybeacon "82" from (31253'34.746"N, 8125'31.9"W) to (Side A) 31253'36.5"N 081205'44.8"W Skidaway River Daybeacon "52" from (31257'57.459"N, 8123'23.187"W) to (Side A) 31257'59.8"N 081203'22.7"W Skull Cr Daybeacon "4" from (32216'22.337"N, 80244'9.12"W) to and REMOVE PA (Side A) 32216'22.4"N 080244'09.1"W 11509 25th ed., 08/17/96 LAST LNM 23/97 NAD 83

24/97

Tybee Island to Doboy Sound (CGD07) **RELOCATE** Ossabaw Snd N Chan Buoy "9" from (31251'42.415"N, 8121'39.587"W) to 31251'35.9"N 081201'34.3"W Ossabaw Snd N Chan Buoy "11" from (31251'40.874"N, 8123'14.454"W) to 31251'36.4"N 081203'08.6"W Vernon River Daybeacon "82" from (31253'34.746"N, 8125'31.9"W) to 31253'36.5"N 081205'44.8"W 11511 15th ed., 04/13/96 LAST LNM 11/97 NAD 83 24/97 Ossabaw and St. Catherines Sound (CGD07) RELOCATE Ossabaw Snd N Chan Buoy "9" from (31251'42.415"N, 8121'39.587"W) to 31251'35.9"N 081201'34.3"W Ossabaw Snd N Chan Buoy "11" from (31251'40.874"N, 8123'14.454"W) to 31251'36.4"N 081203'08.6"W 11512 54th ed., 09/21/96 LAST LNM 23/97 NAD 83 24/97 Savannah River and Wassaw Sound (NOS SILVER SPRING) (CL-574/97) ADD Tabulations of Controlling Depths (See Enclosure Section) (CGD07) Vernon River Daybeacon "82" from RELOCATE (31253'34.746"N, 8125'31.9"W) to 31253'36.5"N 081205'44.8"W Skidaway River Daybeacon "52" from (31257'57.459"N, 8123'23.187"W) to 31257'59.8"N 081203'22.7"W 11513 21st ed., 06/04/94 LAST LNM 21/97 NAD 83 24/97 St. Helena Sound to Savannah River (CGD07) RELOCATE Skull Cr Daybeacon "4" from (32216'22.337"N, 80244'9.12"W) to and REMOVE PA 32°16'22.4"N 080°244'09.1"W 11514 24th ed., 04/10/93 LAST LNM 22/97 NAD 83 24/97 Savannah River (Savannah to Brier Creek) (NOS SILVER SPRING) (CL-574/97) Tabulations of Controlling Depths (See Enclosure Section) ADD 11516 28th ed., 04/12/97 LAST LNM 23/97 NAD 83 24/97 Port Royal Sound and Island Passages (CGD07) RELOCATE Skull Cr Daybeacon "4" from (32216'22.337"N, 80244'9.12"W) to and

32°16'22.4"N 080°244'09.1"W

REMOVE PA

11521 23rd ed., 03/29/97 LAST LNM 23/97 NAD 83 24/97 (TEMP) Charleston Harbor and Approaches (CGD07) ADD Folly River Buoy "9A" in 32237'58.2"N 079259'25.0"W Buoy "10A" in 32237'55.9"N 079259'25.4"W Buoy "12" in 32238'01.3"N 079259'17.8"W Buov "14A" in 32238'46.4"N 079258'24.9"W (CGD07) RELOCATE Folly River Buoy "11" from (322385.1"N, 7925917.2"W) to 32238'07.5"N 079259'11.9"W 11521 23rd ed., 03/29/97 LAST LNM 23/97 NAD 83 24/97 Charleston Harbor and Approaches (NOS SILVER SPRING) (CLS-329, 578/97; BP-161284-85; BP-160659-60) Tabulations of Controlling Depths (See Enclosure Section) ADD 11522 16th ed., 09/09/95 LAST LNM 20/97 NAD 83 24/97 (TEMP) Stono and North Edisto Rivers (CGD07) ADD Folly River Buoy "9A" in 32237'58.2"N 079259'25.0"W Buoy "10A" in 32237'55.9"N 079259'25.4"W • Buoy "12" in 32238'01.3"N 079259'17.8"W Buoy "14A" in 32238'46.4"N 079258'24.9"W (CGD07) CHANGE Folly River Daybeacon "11" to - Buoy "11" and RELOCATE from (32238'4.164"N, 79259'14.74"W) to 32238'07.5"N 079259'11.9"W 11523 17th ed., 03/29/97 LAST LNM 23/97 NAD 83 24/97 Charleston Harbor Entrance (NOS SILVER SPRING) (CLS-329, 578/97; BP-161284-85; BP-160659-60) ADD Tabulations of Controlling Depths (See Enclosure Section) 11524 42nd ed., 11/09/96 LAST LNM 21/97 NAD 83 24/97 Charleston Harbor (NOS SILVER SPRING) Tabulations of Controlling Depths (See Enclosure Section) ADD 25670 38th ed., 02/03/96 LAST LNM 18/96 NAD 83 24/97 Bahia de San Juan (CGD07) ADD San Juan Coast Guard Mooring Buoy, BW in 18227'43.0"N 066206'53.1"W 25673 14th ed., 11/10/90 LAST LNM 17/97 NAD 83 24/97 Bahia de Mayaguez (NOS SILVER SPRING) (CL-470/97; ,BP-160963) Tabulations of Controlling Depths (See Enclosure Section) ADD

26229 11th ed., 05/06/95 LAST LNM 12/97 WGS 84

Approaches to Guantanamo Bay

(CGD07)

RELOCATE Corinaso Cove Buov "8" from

(19254'53.925"N, 7529'20.307"W) to

075209'20 5"W

26230 12th ed., 01/28/95 LAST LNM 12/97 WGS 84

Guantanamo Bay from Entrance to Caimanera

(CGD07)

RELOCATE Corinaso Cove Buoy "8" from

(19254'53.925"N, 7529'20.307"W) to

075209'20.5"W

V. **NEW ADVANCE NOTICE**

None.

VI. **NEW PROPOSED CHANGES**

None.

NEW GENERAL INFORMATION VII.

Α. **NEW BRIDGE INFORMATION**

FLORIDA-FORT MYERS TO CHARLOTTE HARBOR AND WIGGINS PASS: Bridge Closed.

The State Road 865 Drawbridge, at Big Carlos Pass will remain in the closed position for repairs on Wednesday, June 18, from 8:00 a.m. to 5:00 p.m. Vertical clearance in the closed position is 23 feet above mean high water.

Chart: 11428 CG File: 3044

FLORIDA-INTRACOASTAL WATERWAY-HILLSBORO RIVER-BISCAYNE CREEK: Special Bridge Notice.

The Coast Guard has approved a request from the Middlesex Corporation, contractor for the Florida Department of Transportation, allowing a temporary change in the operating regulations for the East Sunrise Boulevard Drawbridge across the Intracoastal Waterway, mile 1062.6, Ft. Lauderdale, Broward County, Florida, to accommodate structural repairs.

This authorization allows the southeast span of the East Sunrise Boulevard Drawbridge to not open to vessel traffic from 8:00 a.m., June 16, 1997 to 6:00 p.m., June 21, 1997. The East Sunrise Boulevard Drawbridge provides a vertical clearance of 25 feet above mean high water in the closed position and a horizontal clearance of 90 feet between fenders. With one leaf in the closed position, a horizontal clearance of approximately 44 feet remains available for navigation.

Chart: 11467 CG File: 2754

FLORIDA-INTRACOASTAL WATERWAY-BISCAYNE BAY-MIAMI RIVER: Special Bridge Notice.

24/97

19²54'55.8"N

19254'55.8"N

24/97

The Coast Guard has received a request from the Florida Department of Transportation in Miami to allow a temporary change in the operating regulations for the Northwest 12th Avenue Drawbridge across the Miami River, mile 2.1 at Miami, Dade County, Florida, to accommodate mechanical drawbridge repairs.

If authorized, this proposal would allow the Northwest 12th Avenue Drawbridge not to open for vessel traffic from 5:00 p.m. on Sunday, June 29, 1997, through 5:00 a.m. on Monday, June 30, 1997. However, the drawbridge will open if a 30-minute advance notification is provided by the vessel requesting the opening. The vertical clearance of this drawbridge in the closed position is 17 feet above mean high water is the closed position and a horizontal clearance of 94 feet between fenders.

FLORIDA-INTRACOASTAL WATERWAY-BISCAYNE BAY-MIAMI RIVER: Special Bridge Notice. (Cont.)

The Coast Guard is seeking comments on this proposed closure period for the drawbridge and the effect it would have on navigation. Comments should be sent to the address on the cover of this notice and should be mailed to arrive no later than June 24, 1997. If you're unable to respond in writing you can comment by calling Brodie Rich at (305) 536-5117.

Ref: LNM 23-97 CG File: 2460

Chart: 11467

FLORIDA—OKEECHOBEE WATERWAY-CALOOSAHATCHEE RIVER: Temporary Bridge Closure.

The Fort Denaud Swing Bridge, mile 108.2 across the Caloosahatchee River at Labelle, Hendry County, Florida will remain in the closed position, Wednesday, June 18, 1997, between 1:00 p.m. and 7:00 p.m. to facilitate emergency re pairs on the swingspan of this highway bridge. All mariners are requested to schedule their trips through the bridge accordingly because the bridge will be unable to open. Vertical clearance in the closed position is nine feet.

Chart; 11428 CG File: 2009

FLORIDA—OKEECHOBEE WATERWAY-CALOOSAHATCHEE RIVER: Bridge Notice.

The SR 78 Drawbridge at mile 116.0 at Alva will be having its submerged electrical cable replaced from June 18-20, 1997. During this period one half the span will be available at all times for vessel passage and the other span will be opened within 30 minutes by hand for larger vessels. The channel may be blocked at times by the contractor's floating equipment. In the closed position, the bridge provides 15 feet vertical clearance.

Chart: 11428 CG File: 2392

FLORIDA-INTRACOASTAL WATERWAY-SARASOTA HARBOR: Bridges Closed.

Sarasota Police Department has asked permission to keep the Ringling Causeway and New Pass Bridges times from 8:30 p.m. until 11:3 p.m. on July 4 th, 1997. During this period the bridges would open on the hour and half hour to pass vessel traffic. This will facilitate the movement of the vehicular and pedestrian traffic during the beach front fireworks display.

Comments on this proposal should be sent to the address on the cover of this notice by June 23, 1997.

Chart: 11425 CG Files: 2394/2596

FLORIDA-INTRACOASTAL WATERWAY-CHARLOTTE HARBOR TO TAMPA BAY-GASPARILLA SOUND: Bridge Notice.

Gaspar Incorporated has advised the Boca Grand Bridge Swingbridge, mile 34.3 is repaired and operated on vessel signal.

Ref: LNM 20-97 CG File: 2877

Chart: 11425

B. MISCELLANEOUS INFORMATION

SOUTH CAROLINA-WINYAH BAY-GEORGETOWN: Harborwalk Boat Races.

The annual Harborwalk Boat Races will be held on the Sampit River at East Bay Park, Georgetown, South Carolina, on June 29, 1997, from 1:00 p.m. and 5:00 p.m. Non-participating vessels are prohibited from operating near the race course area without the permission of the Coast Guard Patrol Commander. There will be approximately 60 high performance speed boats participating.

Chart: 11532

SOUTH CAROLINA-PORT ROYAL SOUND: Dredging Operations.

The dredge BILL JAMES is conducting operations on the west end of Joiner Bank, inside of Port Royal Sound, dredging the existing sand bar from June 12 to June 26, 1997. A floating pipeline will be utilized during the dredging process and will be lighted at night.

Chart: 11516

GEORGIA-SAVANNAH RIVER: Current Meter Installed.

The Ocean & Lake Levels Division of National Ocean Service has deployed a current meter in the Savannah River Entrance on May 07, 1997, in 36 feet of water in position 32²02.139'N 080²53.417'W. The current meter uses an acoustic frequency of 300 kHz to measure the currents. This self-contained system is enclosed in a truncated conical-shaped fiberglass platform that rests on the sea floor. The platform has approximately a seven foot diameter and stands less than two feet off the bottom.

Chart: 11514

FLORIDA KEYS-WHALE HARBOR: Slow Speed/Minimum Wake Zone.

A slow speed/minimum wake zone has been established in Whale Harbor Channel between WHALE HARBOR LIGHT 1 (LLNR 11560) and - Daybeacon 9 (LLNR 11605).

Chart: 11442

VIII. LIGHT LIST CORRECTIONS

(1) (2) (3) (4) (5) (6) (7) (8)

No. Name and Location Position Characteristic Ht Rng Structure

Remarks

None.

IX. ADDITIONAL ENCLOSURES

Enclosure (1) Report of Channel Conditions for Brunswick Harbor Ship Channel fro the Sea to the Upper Limits of the Harbor at Mile 12.76 in Turtle River and East River, Academy Creek and Terry Creek.

Enclosure (2) Tabulations of Controlling Depths for Charts: 11506, 11512, 11514, 11521, 11523, 11524, and 25673.

N. T. Saunders Rear Admiral, U.S. Coast Guard Commander, Seventh Coast Guard District